

General Environmental Incident Summary

Incident: 152 **Date/Time Notice:** 4/6/1992 1205 **DEM Incident No:**

Responsible Party: United Parcel Service

Date Incident: 4/2/1992 **Time Incident:** **Duration:**

County: Burleigh **Twp:** 139 **Rng:** 80 **Sec:** 23 **Qtr:** SE SE

Lat: 46.84524 **Long:** -100.74120 **Method:** Derived from TRS

Location Description: UPS BUILDING AT 3814 FRANKLIN BISMARCK.

Submitted By:

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Todd Krenelaa
3814 Franklin
Bismarck, ND

Distance Nearest Occupied Building:

Type of Incident: HYDROCARBON

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 15.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance:

Reported to NRC: No

Cause of Incident:

TRANSPORT TRUCK OVERFLOWED WHILE FILLING. SOIL IS BEING REMOVED.

Risk Evaluation:

of Fatalities:

of Injuries:

Affected Medium:

Potential Environmental Impacts:

Action Taken or Planned:

Wastes Disposal Location:

Agencies Involved:

